

Inspection checklist for furniture

AQL - Cr: Not allowed / Maj: 2.5 / Min: 4.0

Inspection plan	Requirement	Inspection level	Cr	Maj	Min
Package / packing method	<ol style="list-style-type: none"> 1. Complete, clean and correct 2. Appliance packed into materials to provide protection against transport damage 3. Accessories are complete. 	G-II		*	*
Sales packaging	<ol style="list-style-type: none"> 1. CE mark for Europe shipment missing 2. Required warning or marking missing 3. The warning must be in the official language(s) of the country in which the product is sold. 	G-II	*		
Carton surface	<ol style="list-style-type: none"> 1. Print on the carton in accordance with the specs (including barcode) 2. Shipping mark is OK (order no., item no., etc.) 	G-II		*	*
Appearance	<ol style="list-style-type: none"> 1. Surface without defects / scratches 2. No deformation 3. No sharp edges or points 4. Handle not cracked or loose 5. Base should not be convex or too concave 6. Colour deviation 7. Painting fade out 8. Pitted surface 9. Poor coating / painting / spraying / printing / powder coating. 10. Exposed nail end 11. Incomplete rivet 12. Loose rivet 13. Protruding screw end / head 14. Slant rivet 15. Slipped screw 	G-II	*	*	*