


### Lighting Chains Inspection



ITEM 257607



ITEM 257607



Defect: broken sleeve



Defect: broken sleeve

